SECLET OTCART

25X1A HANDLE VIA CCHTROL SYSTEM

25X1A

13 January 1966

MEMORANDOM FOR THE RECORD

Aborted Flight of Article 125 on 12 January Due SHAIRCT : Migh Oil Pressure Indication.

- 1. A flight of article 125 was aborted on 12 Jamesry one to a high oil pressure indication on the left engine. It has now been established that the problem occurred as a result of faulty operation of the oil pressure transmitter and the faulty transmitter has been replaced.
- 2. The oil pressure transmitters are a LAC supplied item. The currently used transmitter is supplied to LAC by Bendix and is the so-called -58 model. Introduction of this improved model, after the rash of transmitter problems experienced in September and October, has generally resulted in more satisfactory transmitter performance in recent months. Problems still do occur with this transmitter, however, and the recent trouble has been primarily with the synchro slip rings. A fix for this problem is currently being tested by Bendix.
- 3. In addition, LAC is now evaluating a Company transmitter. This is not a high temperature unit, so a fuel cooling jacket has been built and it is now undergoing oven tests. Vibration tests have been completed successfully and a unit will be ready for flight testing this month.

25X1A

25X1A

SIGNED.

25X1A

Aircraft Systems Division (Special Activities)

GICART

EARDLE VIA CONTROL STATES

Approved For Release 2002/09/04: CIA-RDP68B00724R000100020014-4

Approved For Release 2002/09/04: CIA-RDP68B00724R000100020014-4

ANCRET OXCART

25X1A

HANGLE VIA _____

2119-66

25X1A

25X1A

gp (ASD/OSA) 13 Jan 66

Distribution:

Cy 1,2 - ASD/OSA

3 - DD/SAT

4 - D/OSA

5 - D/TECH/OSA

6 - AD/TECH/OSA

7 - chrono

8 - RB/OSA

OXCART

HANGLE VIA CONTROL SYSTEM

25X1A